General Safety Rules in a Carpentry / Joinery Workshop



Wear ear protection!
Min. damping 20dB



Wear tight clothes!



Wear safety shoes with iron cap!



No open Flame!



Helmets are not allowed in Carpentry workshops!
They limit field of vision and don't allow the use of ear protections!



Never wear gloves while you work with machines!

They can be pulled in



Don't wear any Jewellery like Rings, Bracelets, Watches, ...!



Never run in the Workshop!



All machines & electrical installations have to be installed by professional Electricians! In Case of damage or failure interrupt the power supply and request an expert.

Do NOT try to fix it on your own! You may risk your life and the life of others!















